

Индикаторы температурные CARL ROTH

Технические характеристики

Алматы (7273)495-231
Ангарск (3955)60-70-56
Архангельск (8182)63-90-72
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Благовещенск (4162)22-76-07
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Владикавказ (8672)28-90-48
Владимир (4922)49-43-18
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89

Иваново (4932)77-34-06
Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Коломна (4966)23-41-49
Кострома (4942)77-07-48
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Курган (3522)50-90-47
Липецк (4742)52-20-81

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Ноябрьск (3496)41-32-12
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16
Петрозаводск (8142)55-98-37
Псков (8112)59-10-37
Пермь (342)205-81-47

Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Саранск (8342)22-96-24
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13
Сыктывкар (8212)25-95-17
Тамбов (4752)50-40-97
Тургут (3462)77-98-35
Тверь (4822)63-31-35

Тольятти (8482)63-91-07
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Улан-Удэ (3012)59-97-51
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Чебоксары (8352)28-53-07
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Чита (3022)38-34-83
Якутск (4112)23-90-97
Ярославль (4852)69-52-93

Россия (495)268-04-70

Казахстан (772)734-952-31

Киргизия (996)312-96-26-47



Temperature measurement



Colour-change chalk irreversible

ROTH SELECTION.

For temperature monitoring by colour change on devices and apparatus. Adhere to paper, rubber, textiles, plastic, glass, iron and steel. Can also be used in processing aluminium, enamel processing and smelting. Colour changes when the temperature is reached within 1–2 seconds.

Temperature (°C)	Temperature accuracy	Art. No.	Pack Qty.	
120	±5 °C	9307.1	1 unit(s)	
245	±5 °C	9312.1	1 unit(s)	
600	±5 °C	9547.1	1 unit(s)	



Temperature measuring strips irreversible

ROTH SELECTION.

Self-adhesive. Show that the specific temperature value has been reached on surfaces. The light indicator points become dark as soon as the required temperature value is reached. Dimensions per measuring strip: L 48 x 18 mm. Packaged in bags with 10 strips each.

Temperature (°C)	Temperature accuracy	Art. No.	Pack Qty.	
40-43-46-49-54-60-66-71	±1 °C	1890.1	10 unit(s)	
77-82-88-93-99-104-110-116	±1 °C (77–99 °C), ±1.5 °C (100–116 °C)	2077.1	10 unit(s)	
121-127-132-138-143-149-154-160	±1.5 °C (121–154 °C), ±2.6 °C (160 °C)	2079.1	10 unit(s)	
166-171-177-182-188-193-199-204	±(1 °C + 1 % of the measured value)	5231.1	10 unit(s)	
210-216-224-232-241-249-254-260	±(1 °C + 1 % of the measured value)	5232.1	10 unit(s)	



Chargenzettel	
Datum	15.3.94
Rohlings-Nr.	384
Nr. des Kochverfahrens	17
Kammer-Nr.	3
Prozessanfang/-ende	5 ^h /11 ^h
Endtemperatur	77 °C

Temperature measuring point irreversible

ROTH SELECTION.

Self-adhesive, temperature stable foil with heat-sensitive elements for temperature monitoring and testing. Irreversible colour change of light grey or yellow field to black occurs within one second as soon as the required temperature is reached. Dimensions per measuring point: L 15 x W 14 mm.

1 sheet with 50 measuring points.

Temperature (°C)	Temperature accuracy	Art. No.	Pack Qty.	
65	±1,5 °C	N276.1	50 unit(s)	
77	±1,5 °C	N278.1	50 unit(s)	
82	±1,5 °C	N279.1	50 unit(s)	
121	±1,5 °C	N286.1	50 unit(s)	



Temperature indicators mini irreversible

ROTH SELECTION.

Self-adhesive, temperature stable foil with heat-sensitive elements for temperature monitoring and testing. Particularly suited to temperature checking on small objects. An irreversible colour change takes place within two seconds as soon as the required temperature is reached. One sheet with 10 indicators (ø 15 mm per measuring point).

Temperature (°C)	Temperature accuracy	Art. No.	Pack Qty.	
88-93-99-104-110	±1,5 °C	AY04.1	10 unit(s)	
116-121-127-132-138	±1,5 °C	AY05.1	10 unit(s)	
143-149-154-160-166	±2 °C (143 – 154 °C), ±(1 °C + 1 % of reading) from 160 °C	AY06.1	10 unit(s)	

Алматы (7273)495-231
Ангарск (3955)60-70-56
Архангельск (8182)63-90-72
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Благовещенск (4162)22-76-07
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Владикавказ (8672)28-90-48
Владимир (4922)49-43-18
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89

Иваново (4932)77-34-06
Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Коломна (4966)23-41-49
Кострома (4942)77-07-48
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Курган (3522)50-90-47
Липецк (4742)52-20-81

Россия (495)268-04-70

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Ноябрьск (3496)41-32-12
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16
Петрозаводск (8142)55-98-37
Псков (8112)59-10-37
Пермь (342)205-81-47

Казахстан (772)734-952-31

Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Саранск (8342)22-96-24
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13
Сыктывкар (8212)25-95-17
Тамбов (4752)50-40-97
Сургут (3462)77-98-35
Тверь (4822)63-31-35

Киргизия (996)312-96-26-47

Тольятти (8482)63-91-07
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Улан-Удэ (3012)59-97-51
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Чебоксары (8352)28-53-07
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Чита (3022)38-34-83
Якутск (4112)23-90-97
Ярославль (4852)69-52-93